
607 NW 27th Ave Ocala, FL 34475 Phone : (352) 629-5020 Fax : (352)-629-2902	R	EBUILD INSTRUCTIONS	P/N	SB-161		
	TYPE	INTAKE F	RELIEF '	VALVE	PAGE	1 OF 9
	DEPARTMENT	ACCESSORIES	ВҮ	SEAN LYONS	REV	A

The following tools and supplies are required to complete this procedure:

- Small adjustable crescent wrench
- Large adjustable crescent wrench up to 1-3/8" span
- Channel locks
- Flat head screwdriver
- Anti-seize
- Alcohol
- Clean rag

All replacement parts are to be ordered separately, in the intake relief valve rebuilt kit, which include:


- 073-00015-000 replacement piston
- 097-2620-00-0 sealing washer
- 040-8260-00-0 o-ring
- 142-0390-00-0 square-cut o-ring seal




REV	DATE	ВҮ	DESCRIPTION	Approved By
Α	13FEB2018	SBL	PRELIMINARY	

HALE
607 NW 27th Ave
Ocala, FL 34475
Phone: (352) 629-5020
Fav · (352)-629-2902

R	EBUILD INSTRUCTIONS	P/N	SB-161		
TYPE	INTAKE F	PAGE	2 OF 9		
DEPARTMENT	ACCESSORIES	ВҮ	SEAN LYONS	REV	Α





REV	DATE	ВҮ	DESCRIPTION	Approved By
Α	13FEB2018	SBL	PRELIMINARY	






SB-161


3 OF 9


Α



REV	DATE	ВҮ	DESCRIPTION	Approved By
Α	13FEB2018	SBL	PRELIMINARY	

HALE	R	REBUILD INSTRUCTIONS (PRELIMINARY)					
607 NW 27th Ave Ocala, FL 34475 Phone : (352) 629-5020 Fax : (352)-629-2902	TYPE	INTAKE R	INTAKE RELIEF VALVE				
	DEPARTMENT	ACCESSORIES	BY	SEAN LYONS	REV	Α	







REV	DATE	ВҮ	DESCRIPTION	Approved By
Α	13FEB2018	SBL	PRELIMINARY	



R	EBUILD INSTRUCTIONS	P/N	SB-161		
TYPE	INTAKE F	PAGE	5 OF 9		
DEPARTMENT	ACCESSORIES	ВҮ	SEAN LYONS	REV	Α







REV	DATE	ВҮ	DESCRIPTION	Approved By
Α	13FEB2018	SBL	PRELIMINARY	



R	EBUILD INSTRUCTIONS	P/N	SB-161		
TYPE	INTAKE F	PAGE	6 OF 9		
DEPARTMENT	ACCESSORIES	BY	SEAN LYONS	REV	Α







REV	DATE	ВҮ	DESCRIPTION	Approved By
Α	13FEB2018	SBL	PRELIMINARY	



R	EBUILD INSTRUCTIONS	P/N	SB-161		
TYPE	INTAKE F	PAGE	7 OF 9		
DEPARTMENT	ACCESSORIES	BY	SEAN LYONS	REV	Α







REV	DATE	ВҮ	DESCRIPTION	Approved By
Α	13FEB2018	SBL	PRELIMINARY	

HALE
607 NW 27th Ave
Ocala, FL 34475
Phone: (352) 629-5020
Eav : (2E2) 620 2002


R	EBUILD INSTRUCTIONS	P/N	SB-161		
TYPE	INTAKE F	PAGE	8 OF 9		
DEPARTMENT	ACCESSORIES BY		SEAN LYONS	REV	Α





REV	DATE	ВҮ	DESCRIPTION	Approved By
Α	13FEB2018	SBL	PRELIMINARY	

HALE	R	REBUILD INSTRUCTIONS	P/N	SB-161		
607 NW 27th Ave	TYPE	INTAKE F	PAGE	9 OF 9		
Ocala, FL 34475 Phone : (352) 629-5020 Fax : (352)-629-2902	DEPARTMENT	ACCESSORIES	ВҮ	SEAN LYONS	REV	Α



Conclude this replacement by remounting the intake relief valve on the pump, repeating this procedure on any other desired intake relief valves on the pump, and lastly conducting a standard pump air leak test.

REV	DATE	ВҮ	DESCRIPTION	Approved By
Α	13FEB2018	SBL	PRELIMINARY	