Hale Fire Pump Company 708 Spring Mill Avenue Conshohocken, Pa. 19428 (215) 828-8835

## HALE PUMPS

September 11, 1975

## SERVICE BULLETIN #27

TO: HALE MIDSHIP PUMP CUSTOMERS

SUBJECT: Discharge Valves

Gentlemen:

The reliable BL and B discharge valves, produced by Hale, have been the standard in the industry for many years.

During the valve assembly process, we coat the balls with a waterproof grease to provide long seal life and to keep the valve turning freely. This coating should be replaced on a routine basis to ensure easy opening valves.

If you have an occasion where sticky valves persist, you could add one thin gasket (BL part number BL-11 or B part number B-11) between the cover and the body or in extreme cases, a thick gasket (BL part number BL-W11 or B part number B-W11) to reduce the pre-load on the ball.

A shot of oil on the remote control linkages will greatly assist in keeping them working freely.

Sincerely,

HALE FIRE PUMP COMPANY

Fred Buchler Service Manager

FB:jz

